ชื่อเรื่องวิทยานิพนธ์

การประยุกต์ระบบสารสนเทศภูมิศาสตร์ในการศึกษาเพื่อการ พัฒนาประปาหมู่บ้าน: กรณีศึกษา อำเภอเกาะคา จังหวัดลำปาง

ชื่อผู้เขียน

นางกัลยาณี สุวรรณประเสริฐ

วิทยาศาสตรมหาบัณฑิต

สาขาวิชาภูมิศาสตร์

คณะกรรมการสอบวิทยานิพนธ์ ผู้ช่วยศาสคราจารย์ ดร.พงษ์อินทร์ รักอริยะธรรม ประธานกรรมการ รองศาสตราจารย์ คร. เสน่ห์ ญาณสาร รองศาสตราจารย์ พวงเพชร์ ธนสิน กรรมการ อาจารย์ คร. ชูศักดิ์ วิทยาภัก กรรมการ

## บทคัดย่อ

การประยุกต์ใช้ระบบสารสนเทศภูมิสาสตร์ในการศึกษาเพื่อพัฒนาศักยภาพของประปา หมู่บ้าน มีวัตถุประสงค์เพื่อ (1) ศึกษาสภาพปัญหา สถานภาพทางคุณภาพและปริมาณของน้ำสะอาด ที่ใช้อุปโภคบริโภคในระดับหมู่บ้าน (2) ศึกษารูปแบบ วิธีการ และปัญหาในการจัดการประปาหมู่บ้าน (3) ประเมินศักยภาพของประปาหมู่บ้าน และ (4) ประยุกต์ระบบสารสนเทศภูมิศาสตร์ในการจัดทำ ฐานข้อมูลประปาหมู่บ้าน และประเมินความเหมาะสมเชิงพื้นที่สำหรับจัดสร้างประปาหมู่บ้านของ อำเภอเกาะคา จังหวัดลำปาง วิธีการศึกษาประกอบด้วยการวิเคราะห์ข้อมูลด้วยระบบสารสนเทศ ภูมิศาสตร์ การสำรวจภาคสนาม การสัมภาษณ์ประชาชนในพื้นที่และผู้มีส่วนเกี่ยวข้อง และการวิเคราะห์ ข้อมลที่ได้มีการศึกษาไว้แล้ว

ผลการศึกษาทางด้านปัญหา และสถานภาพของน้ำสะอาดในอำเภอเกาะคาพบว่า ด้านคุณภาพน้ำมีปัญหาที่ส่งผลกระทบต่อประชาชนมากที่สุดคือปัญหาปริมาณสารฟลูออไรด์เจือปน ในน้ำอุปโภคบริโภคเกินมาตรฐาน รองลงไปเป็นปัญหาสนิมเหล็ก และปัญหาทางด้านแบคทีเรีย สำหรับปัญหาทางค้านปริมาณน้ำพบว่ามีหมู่บ้านในอำเภอเกาะคาที่มีปัญหาขาดแคลนน้ำอุปโภค บริโภค มีจำนวน 14 หมู่บ้าน โดยปัญหาจะมีความรุนแรงในช่วงฤดูแล้ง ผลกระทบจากปัญหา น้ำอุปโภคบริโภค ที่พบมาก คือ ปัญหาฟลูออไรด์เป็นพิษซึ่งทำให้เกิดโรคฟันกระและกระลูกผุ ซึ่งจะพบมากบริเวณทางตอนเหนือของอำเภอเกาะคา รวมทั้ง ปัญหาการอุดตันของระบบท่อ ปัญหาภาชนะหุงต้มเสียหาย

ในด้านรูปแบบ วิธีการ และปัญหาในการจัดการ พบว่าประปาหมู่บ้านในอำเภอเกาะกา สามารถแบ่งได้เป็น 2 รูปแบบ คือ ประปาหมู่บ้านที่สร้างด้วยงบประมาณภาครัฐ และประปาหมู่บ้าน ที่สร้างขึ้นด้วยงบประมาณชุมชน ปัญหาการจัดการประปาหมู่บ้านของอำเภอเกาะคา ซึ่งมีความเกี่ยวเนื่อง โยงใยซึ่งกันและกัน สามารถแบ่งได้เป็น 3 กลุ่มใหญ่ ๆ คือ ปัญหาการจัดการอันเนื่องมาจากลักษณะ ของแหล่งน้ำ ปัญหาการจัดการด้านโครงสร้างและการผลิตน้ำประปา และปัญหาการจัดการ ด้านบริหารกิจการ ปัจจัยที่มีผลต่อปัญหาและศักยภาพของประปาหมู่บ้าน ได้แก่ นโยบายของรัฐ การจัดการน้ำโดยประชาชนเองโดยภาครัฐมิได้เจ้าไปติดตามให้คำแนะน้ำ การมีส่วนร่วมของ ประชาชน ซึ่งพบว่ามีส่วนอย่างมากต่อการเกิดขึ้นของปัญหาทางด้านการจัดการ ลักษณะขององค์กร ควรจะมีการผสมผสานระหว่างองค์กรที่องถิ่นและรัฐส่วนท้องถิ่น นอกจากนี้บทบาทของผู้นำชุมชน คณะกรรมการหมู่บ้าน และกฎ กดิกาการใช้น้ำยังมีผลด้วย

การประยุกต์ใช้ระบบสารสนเทศภูมิศาสตร์ในการประเมินศักยภาพของประปาหมู่บ้าน และความเหมาะสมเชิงพื้นที่สำหรับจัดสร้างประปาหมู่บ้าน พบว่าศักยภาพของแหล่งน้ำผิวดิน โดยเฉพาะในด้านการไหลบ่าบนผิวดินส่วนใหญ่อยู่ในระดับปานกลาง คือ ร้อยละ 47.09 ของพื้นที่ทั้งหมด โอกาสที่จะเกิดการปนเปื้อนของแหล่งน้ำผิวดินที่ใช้ผลิตประปามีโอกาสที่จะเกิดการปนเปื้อนอยู่ใน ระดับค่อนข้างต่ำ มีความเสี่ยงจากยาฆ่าแมลง และสารในเตรตอยู่ในระดับสูง และมีเสถียรภาพของ แหล่งผลิต ซึ่งประกอบด้วยลักษณะเฉพาะของประปา และวิธีการดำเนินการดูแลรักษาอยู่ในระดับค่อนข้างสูง สำหรับประปาหมู่บ้านที่มีเสถียรภาพต่ำ เมื่อพิจารณาศักยภาพโดยรวมของประปาผิวดิน พบว่ามีศักยภาพดำจนถึงสูงอยู่จำนวนใกล้เกียงกัน ทั้งนี้เนื่องจากมีการดูแลจัดการการปนเปื้อน ที่แตกต่างกัน สำหรับศักยภาพของประปาบาดาล พบว่าแหล่งน้ำใต้ดินโดยทั่วไปมีคุณภาพสูงเหมาะที่จะนำ มาผลิตเป็นน้ำประปา แต่มีศักยภาพในเชิงปริมาณในระดับปานกลาง โอกาสที่จะเกิดการปนเปื้อน อยู่ในระดับค่อนข้างค่ำเป็นส่วนใหญ่ แหล่งผลิตน้ำประปาบาดาลส่วนใหญ่มีเสถียรภาพอยู่ในระดับปานกลาง ซึ่งควรมีการตรวจสอบติดตามผล รวมทั้งการให้คำแนะนำในข้อบกพร่องที่เกิดขึ้นใน กระบวนการผลิตน้ำประปา

Thesis Title

Application of Geographic Information Systems to the

Study of Village Piped Water Supply Development: A Case

Study of Amphoe Ko Kha, Changwat Lampang

Author

Mrs. Kalyanee Suwanprasert

M.S.

Geography

**Examining Committee** 

Associate Professor Dr. Pong-in Rakariyatham Chairman
Associate Professor Dr. Sanay Yarnasarn Member
Associate Professor Puangpetch Dhanasin Member
Lecturer Dr. Chusak Witayapak Member

## ABSTRACT

The objectives of the "Application of Geographic Information Systems to the Study of Village Piped Water Supply Development: A Case Study of Amphoe Ko Kha, Changwat Lampang" are: (1) to study problems, quality and quantity status of drinking water consumption at village level, (2) to examine patterns, methods and problems in village piped water supply management, (3) to evaluate village piped water supply potential, and (4) to apply Geographic Information Systems (GIS) to preparation of village piped water database and estimate spatial suitability for village piped water supply in Amphoe Ko Kha, Changwat Lampang. The methods of the study include data analysis by applying GIS, field survey and interviewing local people and involved persons and also analysis of data from secondary sources.

The result of study indicates that the problem affecting people most are fluoride dissolved in water consumption higher than the standard limit, followed by iron-ion (Fe) and bacteria. There are 14 villages which have water shortage problem especially during the dry season. The impact of problem includes fluorosis effect causing teeth and bone decay which is most found in the northern part of study area, and the problem with pipe clogged up and kitchen utensil corrosion.

The pattern of piped water supply can be divided into 2 types, village piped water supply built by government fund and village piped water supply built by using local community fund. There are 3 inter-related management problems: problem involving with water source, structure and processing of piped water, and administration problem. The factors leading to management problems and potential of village piped water supply are government policy, water management by local people without any recommendations of government sector, and lack of people participation which is the major cause of management problem. The combination between local organization and local government is preferable kind of organization in village piped water supply management. Besides, village leaders and committees together with rules and regulations applying in water consumption also play role in management.

The application of GIS to evaluation of potential and spatial suitability for village piped water reveals that 47.09 percent of total study area has medium potential in surface runoff. Contamination of general surface water is at medium-low level, but the risk from pesticides and nitrate substance is at high level. Stability of water source for surface piped water supply including characteristics of piped water and maintenance, is at medium-high level. However, there is the same number of villages with low to high stability. Considering overall potential of surface piped water supply, it can be found that the result is almost the same because surface piped water has high possibility to be contaminated with pollution and has many different steps in maintenance. The underground water supply has high quality suitable for using as water source for piped water supply, but its quantity is at only medium level. The contaminated probability is at medium level and medium-low potential for each piped water supply. Stability of underground water source is at medium level. In general, potential of underground piped water supply in Amphoe Ko Kha is at medium level which should be monitored and advised regularly.